
SIMPLE PLEATED FACE MASK



Be sure to use two layers of woven fabrics so that your mask will pass the candle test (can't blow out a candle wearing the mask). This mask design is a bit smaller, so feel free to make adjustments as needed. Finished size is $7 \frac{1}{2}$ x $4 \frac{1}{2}$.

Supplies:

- -Fat quarter of fabric (can use different or same for lining fabric)
- -Nose wire
- -Adjustable elastic
- -Thread
- 1. Cut two pieces of fabric, each 8 ½" x 5 ½".
- 2. Lay fabric together with wrong sides facing. Starting around $1 \frac{1}{2}$ " from the top, fold and press two pleats, as shown in fig. A.
- 3. On the front of one piece of fabric, place the elastic ends 1/2" from the top and bottom corners, and stitch 1/8" along the edge. Repeat on the other side. See fig. B.
- 4. Place fabrics right sides together, being sure to align pleat folds facing down. Stitch around, using a ½" seam allowance, leaving an opening at the bottom. Zig-zag stitch along sides to secure elastic. See fig. C.
- 5. Insert nose wire in between fabric layers at the center top seam and stitch on three sides to secure it, as shown in fig. D.
- 6. Clip corners, turn right sides out, then poke out corners, press, and topstich along the opening.

